



**Product / Process Change Notification
OI-PCN-2020-07-01**

Obsolescence of -R Variants

**Issue Date:
20th July 2020**

1 Affected Products

Part Number	Description
OI-G1480-R	Swift GenICam Camera - Standard with Silicone Rubber Ends
OI-G1481-R	Swift GenICam Camera - Medium with Silicone Rubber Ends
OI-G1482-R	Swift GenICam Camera - Narrow with Silicone Rubber Ends

Table 1: List of affected products

2 Reason for change

To improve manufacturing capacity, we have streamlined production of Swift products.

3 Details of change

As part of the streamlining process, it was decided to remove support for production of devices with silicone rubber ends (designated with a -R suffix) due to limited customer uptake.

Discontinued Product	Description
OI-G1480-R	Swift GenICam Camera - Standard with Silicone Rubber Ends
OI-G1481-R	Swift GenICam Camera - Medium with Silicone Rubber Ends
OI-G1482-R	Swift GenICam Camera - Narrow with Silicone Rubber Ends

Table 2: Discontinued Products

Original Product	Replacement Product	Description
OI-G1480-R	OI-G1480	Swift GenICam Camera - Standard
OI-G1481-R	OI-G1481	Swift GenICam Camera - Medium
OI-G1482-R	OI-G1482	Swift GenICam Camera - Narrow

Table 3: Replacement products

Customers who have previously purchased -G variants will find that the replacement devices have exactly the same performance and mechanically drop in to existing installations.

4 Last time buy

No last time buy is available. Affected customers have been contacted directly.

5 Customer Actions

Customers may need to update their ordering systems with the replacement products.

6 Customer Support

Should any customer have concerns or problems regarding this notification, please contact Odos Imaging at: support@odos-imaging.com.

The information provided in this notification are subject to change without notice. For the latest version of this document, please visit www.odos-imaging.com.