



**Product / Process Change Notification
OI-PCN-2018-12-01**

**Connector Upgrade and Product Discontinuation
OI-SW-048x Family**

**Issue Date:
December 14, 2018**

1 Affected Products

Product	Description
OI-SW-0480	StarForm-Swift, STD FoV
OI-SW-0481	StarForm-Swift, MID FoV
OI-SW-0482	StarForm-Swift, NAR FoV

Table 1: List of affected products

2 Reason for change

Customer request for connector upgrade.

3 Details of change

We have upgraded the power and GPIO connectors to M12 versions on our StarForm-Swift products. To reflect the upgrade we have created new products (and part numbers), and have discontinued the old products.




Figure 1: Rear of StarForm-Swift with original connectors




Figure 2: Rear of StarForm-Swift with replacement M12 connectors

4 Last time buy

The OI-SW-048x products have been replaced with immediate effect.

5 Possible Successor

Other than the upgrade of connector to M12 variant, the replacement products are fully compatible with the original products.

Original Product	Replacement Product	Description
OI-SW-0480	OI-SW-1480	StarForm-Swift, STD FoV
OI-SW-0481	OI-SW-1481	StarForm-Swift, MID FoV
OI-SW-0482	OI-SW-1482	StarForm-Swift, NAR FoV

Table 2: Replacement products

6 Customer Actions

None required. Customers who have ordered OI-SW-048x products will be contacted, and will have option to change to OI-SW-148x. Customers ordering original products will be advised at the time of ordering.

7 Customer Support

Should any customer have concerns or problems regarding this notification, please contact Odos Imaging at: support@odos-imaging.com.

The information provided in this notification are subject to change without notice. For the latest version of this document, please visit www.odos-imaging.com.